















## Natura Onecoat

# **WOOD OIL 2K**

## General Features:

One coat stain and finish for all interior wooden surfaces, including flooring, cabinets and furniture, providing extra durable protection against stains, water and heat. Compatible with most wood types, it maintains the natural appearance without forming a surface film layer.

Fast drying: the wooden surface becomes touch dry within 1 hour after application.

Outstanding yield and coverage, 360 mL (12.17 oz.) could cover 120-215 sq. ft. wooden surface depending on the wood type, sanding and application method. Available in multiple colors, all of which can be mixed together.

Very low odor with a light oil scent.

Easy application and maintenance without overlap.

VOC Free and environmentally friendly.

EN 71-3 certified and MEKO free.

# **Tecnical Specifications:**

Basis : Mixture of natural oils and waxes.

Physical form : Liquid.

Density : Clear: 0.93-0.95 g/cm³; Colors: 1.00-1.40 g/cm³

VOC (2004/42/CE,1999/13/CE) : 0 g/

Resistance to water (NEN-EN 13442) : No visual or tangible changes.

Resistance to wear : High abrasion and scratch resistance.

Shelf life (5-35°C) : 2 years for unopened can.

# Surface Preparation:

Clean the surface thoroughly; remove any dirt and dust from the surface.

Sand the surface with  $80/120~\mathrm{grit}$  screen for flooring and  $180/220~\mathrm{grit}$  for furniture.

Vacuum clean the surface to remove the generated dust and remove the remaining dust with a microfiber cloth.

#### Application:

The product is used as two components with a ratio of oil to hardener 3:1. Do not dilute the product.

360 mL of product could cover 10-18m² wooden surface depending on the wood type and application method.

Stir well the product before use. Mix 3 parts wood oil 2K-A with 1 part wood oil 2K-B (Hardener). Stir well after mixing.

The mixture has a pot life of 5-6 hours after preparation.

Apply the mixture in one coat with a spreader, cloth, or an application pad.

Remove the excess oil by a clean cloth after 3 minutes, until surface feels dry.

Applied surface may be stepped on after 24 hours.

It takes 5 days for full cure.

## Safety Precautions:

CLOTHS THAT ARE SOAKED WITH OIL MAY SPONTANEOUSLY COMBUST. AFTER USAGE, WASH THE CLOTHS WITH WATER BEFORE DISPOSAL!

